




1/5

FIG. 1

FIG. 2

3/5FIG. 3a

SUPPLYING								
	P1	P2	P3	P4	P5	P6	P7	P8
FED								
P1	1	0	1	1	1	1	1	1
P2	0	1	1	1	1	1	1	1
P3	0	0	1	0	1	1	1	1
P4	0	0	0	1	0	0	1	1
P5	0	0	0	0	1	0	1	1
P6	0	0	0	0	0	1	0	1
P7	0	0	0	0	0	0	1	1
P8	0	0	0	0	0	0	0	1
HS	1	1	3	3	4	4	6	8

FIG. 3b

4/5




FIG. 7.





FIG. 7

5/5

FIG. 5